FortyFive

Site report WO-6001

Cross-connect patching — Birmingham bay 9

JOB
WO-6001 Cross-connect patching — Birmingham bay 9

SITE
Birmingham Example Exchange

ADDRESS
12 Example Row, B1 1AA Birmingham, West Midlands, GB

PARTNER
RuizNet

ENGINEER
Elena Ruiz

ON SITE
13 Oct 2026, 07:59 UTC to 13 Oct 2026, 09:39 UTC

SUBMITTED
13 Oct 2026, 09:39 UTC

Arrive and access

Photograph the room door with its number visible before you start.

Site name *
Birmingham Example Exchange — bay 9
Captured 13 Oct 2026, 08:00 UTC · device location recorded

Access granted on arrival *
Yes
Captured 13 Oct 2026, 08:00 UTC · device location recorded

Room door *



Captured photo
Captured 13 Oct 2026, 08:01 UTC · device location recorded

Patch and label


Patch to the port schedule, label both ends, then photograph each check.

Cabinet label *



Captured photo
Captured 13 Oct 2026, 08:10 UTC · device location recorded

Patch panel after work *




Captured photo
Captured 13 Oct 2026, 08:19 UTC · device location recorded

Switch ports lit *



Captured photo
Captured 13 Oct 2026, 08:28 UTC · device location recorded

Splice tray closed out



Captured photo
Captured 13 Oct 2026, 08:37 UTC · device location recorded

Test

Light level reading *



Captured photo
Captured 13 Oct 2026, 08:46 UTC · device location recorded

Received light level (dBm) *

-3.2

Captured 13 Oct 2026, 09:34 UTC · device location recorded

Visit outcome *

Completed

Captured 13 Oct 2026, 09:35 UTC · device location recorded

Sign-off

Engineer notes

Cross-connects patched to the port schedule and labelled both ends. Link tested end to end at -3.2 dBm.

Captured 13 Oct 2026, 09:37 UTC · device location recorded

Engineer signature *



Captured signature
Captured 13 Oct 2026, 08:55 UTC · device location recorded

The device's location was recorded when the report was submitted. It shows what the device reported, not that the engineer was there. The time beside each answer comes from the device's clock when the answer was first given. Like the location, it is not proof.

Seal

Seal (SHA-256): 6f043fa6cef5310d651debffc697c2c98211469eab0e2e0b69ba82583cf25908
Sealed at 13 Oct 2026, 09:39 UTC · Not signed (sealed only)
When this PDF was produced, the report matched its seal.
Verify at /site-reports/1ae34fbb-34f8-41fe-b885-000519ea9fe9